

Figure 1 -View of streambank scour upstream of Upper Hembree Road.



Figure 2 - View of upper bank failure south of Upper Hembree Road near horse farm.



Figure 3 - View of trees along stream bank north of Hembree Road.



Figure 4 - View of Foe Killer Creek from bridge at Hembree Road.



Figure 5 - View of obstructed box culvert at Alpharetta Highway.



Figure 6 - View of Foe Killer Creek from bridge at Old Roswell Road.



Figure 7 - View of stream bank scour near Rock Mill Way.



Figure 8 - View of stream obstruction from bridge near Rock Mill Way.



Figure 9 - View of stream bank scour near Davis Drive.



Figure 10 -View of wetland area near Foe Killer Creek near Georgia Highway 400.