



Figure 1 - View of Debris in Big Creek.



Figure 2 - View of Big Creek in winter.



Figure 3 - View of streambank erosion on Big Creek.



Figure 4 - View of Big Creek from Old Roswell Road.



Figure 5 - View of localized streambank erosion.



Figure 6 - Fallen trees are the result of streambank erosion on Big Creek.



Figure 7 - View of Big Creek north of Grimes Bridge Road.



Figure 8 - View of Big Creek with little streambank cover.



Figure 9 - View of Big Creek along Oxbo Road.



Figure 10 - View of sewer crossing near Roswell Mill.